Chimney			
Definition:	A vertical channel or pipe designed to convey combustion gases—such as smoke—from a fire or		
	furnace to the outside		
Name Variants:	N/A		
Most Common Materials:	brick, concrete, veneer, block, stucco, wood, vinyl, clay, metal		
Most Common Components:	cap, flashing, flue, liner, crown, damper, pipe		
Reference Images:	[insert pictures or diagrams here.]		

Location & Inspection of Chimney		
Abilities or Knowledge Needed:	- Mobility for a	for location & inspection ccess to all areas of the property g of item's components
Tools for Location & Inspection	Useful: Required:	flashlight None
Common Locations:	Unit/Inside: Outside:	Living rooms or wherever a fireplace, gas, or combustible furnace is located.  Roofs
How to Locate:	Visual Observation:	Look above fireplaces and on roofs in areas that correspond to fireplaces within the building.
Possible Deficiencies:	Deficiency 1: Deficiency 2: Deficiency 3: Deficiency 4: Deficiency 5: Deficiency 6: Deficiency 7:	Chimney is missing Damper will not open or stay open Liner, flue, pipe, or cap is clogged Liner, pipe, or chimney structure (any size) in it Chimney has displaced or missing materials Chimney is displaced, detached, or leaning away from building Chimney surface is damaged

Deficiency 1: Chimney is Missing			
Rationale code(s):	Maintenance:	Indicates maintenance staff is not identifying deficiencies or responding to self-generated or complaint-driven work orders.	
	Health and Safety:	Reduces interior air quality; affects residents with breathing issues; increases probability resident exposure to smoke, sparks, and outside elements such as pests, allergens, and weather.	
	Operability:	Prevents proper use of fireplace/furnace.	
Health and Safety	Severe:	This is a life-threatening or severe health and safety issue requiring a 24-hour repair, correction, or act of abatement.	
How to Inspect:	Visual Observation:	Look on the outside of the building in a location that corresponds directly to an inside fireplace, wood-burning stove, or gas stove.	
Record deficiency if:	Chimney is not presen	t.	

Deficiency 2: Damper will not open or stay open			
Rationale code(s):	Maintenance:	Indicates maintenance staff is not identifying deficiencies or responding to self-generated or complaint-driven work orders.	
	Health and Safety:	Reduces interior air quality; affects residents with breathing issues; increases probability resident exposure to smoke.	
	Operability:	Prevents proper use of fireplace/furnace.	
Health and Safety	Standard:	This is a standard health and safety issued requiring a correction, remedy, or act of abatement within 30 days.	
How to	Request for Help:	Ask the POA representative to open the damper of the chimney.	
	Visual Observation:	Look to see if the damper opens and stays open.	
Record deficiency if:	The damper does not damper.	open, will not stay open, or if the POA representative refuses to open the	

Deficier	ncy 3: Lin	er, flue, pipe, or cap is clogged.
Rationale code(s):	Maintenance:	Indicates maintenance staff is not identifying deficiencies or responding to self-generated or complaint-driven work orders.
	Health and Safety:	Reduces interior air quality; affects residents with breathing issues; increases probability resident exposure to smoke.
	Operability:	Prevents proper use of fireplace/furnace.
Health and Safety	Severe:	This is a life-threatening or severe health and safety issue requiring a 24-hour repair, correction, or act of abatement.
How to Inspect:	Request for Info:	Ask the POA representative for copies of most recent chimney inspection or professional (or self-certification) cleaning.
Record deficiency if:	N/A	

<u>Deficiency 4</u> : Line		er, pipe, or chimney structure has a hole
	(ar	ny size) in it
Rationale code(s):	Maintenance:	Indicates maintenance staff is not identifying deficiencies or responding to self-generated or complaint-driven work orders.
	Health and Safety:	Reduces interior air quality; affects residents with breathing issues; increases probability resident exposure to smoke.
	Operability:	Prevents proper use of fireplace/ gas furnace.
Health and Safety	Severe:	This is a life-threatening or severe health and safety issue requiring a 24-hour repair, correction, or act of abatement.
How to Inspect:	Visual Observation:	Look for a hole of any size on the liner, pipe, or chimney structure that penetrates to the inside of the chimney.
Record deficiency if:	A hole of any size is observed on the liner, pipe, or chimney structure and it penetrates to the inside of the chimney. Maximum of one deficiency per chimney.	

Deficier	<u>ncy 5</u> : Chi	mney has displaced or missing materials
Rationale code(s):	Maintenance:	Indicates maintenance staff is not identifying deficiencies or responding to self-generated or complaint-driven work orders.
	Structural:	Indicates possibility of more extensive structural problems.
	Capital Cost:	Creates increased capital costs if enough masonry across multiple chimneys is present.
	Health and Safety:	Increases probability of falling masonry that could injure residents.
	Public Perception:	Indicates poor quality of property.
Health and Safety	Severe:	This is a life-threatening or severe health and safety issue requiring a 24-hour repair, correction, or act of abatement.
How to Inspect:	Visual Observation:	Look at the areas of the chimney that are 10 feet above ground level and the materials that the chimney is made of—especially if made of brick, block, stone, or clay—as well the areas close by, such as the floor or roof.
Record deficiency if:	•	on the chimney 10 feet from ground level are displaced, missing, loose, or have num of one deficiency per chimney.

<u>Deficier</u>	ncy 6: Chi	imney is displaced, detached, or leaning
away from building		
Rationale code(s):	Maintenance:	Indicates maintenance staff is not identifying deficiencies or responding to self-generated or complaint-driven work orders.
	Structural:	Indicates possibility of more extensive structural problems.
	Capital Cost:	Creates increased capital costs if chimney needs replacing.
	Health and Safety:	Increases probability of falling, which could injure residents.
	Public Perception:	Indicates poor quality of property.
Health and Safety	Severe:	This is a life-threatening or severe health and safety issue requiring a 24-hour repair, correction, or act of abatement.
How to Inspect:	Visual Observation:	Look at the chimney and determine if it is leaning (is not perfectly vertical) or is becoming (or has become) physically separated from the building.
Record deficiency if:	The chimney is leaning	g or is becoming (or has become) physically separated from the building.

Deficiency 7: Chimney surface is damaged			
Rationale code(s):	Maintenance:	Indicates maintenance staff is not identifying deficiencies or responding to self-generated or complaint-driven work orders.	
	Health and Safety:	Creates possibility for exposed lead-based paint if structure was built pre- 1978.	
	Public Perception:	Indicates poor quality of property.	
Health and Safety	Standard:	This is a standard health and safety issue requiring a repair, correction, or act of abatement must occur within [insert timeframe here].	
How to Inspect:	Visual Observation:	Look at the surface materials of chimney to see if there is damage, which includes, but is not limited to missing/cracked/spalling mortar, other cracks, non-penetrating holes, missing siding, and peeling paint.	
Record deficiency if:	Observed damage covers a combined total area of approximately 4 sq. ft. Maximum of one deficiency per chimney.		